Pour tout renseignement, contacter :
SAS FRANCE SECURITE
585 rue Alain Colas
CS 61856
29218 BREST CEDEX 1
Tel : 02 98 80 25 35
www.france-securite.fr

USER INSTRUCTIONS

STARCUT FLEX

S233450

Securitop

Protective gloves reinforced for general use. Total nitrile foam coating. Nitrile dots on the palm. Support based on UHMWPE fibers. Wrist rib-edge.

Notified body used for the EU certificate: SATRA Technology Europe Limited
Bracetown Business Park. Clonee
D15YN2P – REPUBLIC OF IRELAND (n°2777)

EN ISO 21420:2020 : Innocuousness – Comfort – Dexterity : LEVEL 5
EN388 :2016+A1 :2018 : (Levels taken on palm new gloves) :

4X42B

1. **Abrasion : level 4**
2. **Blade cut : level X**
3. **Tearing : level 4**
4. **Puncture : level 2**
5. **Cut resistance TDM : level B**

LEVEL	1	2	3	4	5
Abrasion resistance (Number of cycles)	100	500	2000	8000	-
Blade cut resistance (Index)	1.2	2.5	5.0	10.0	20.0
Tear resistance (N)	10	25	50	75	-
Puncture resistance (N)	20	60	100	150	-

TEST	Level A	Level B	Level C	Level D	Level E	Level F
Straight blade cut (TDM) resistance (N)	2	5	10	15	22	30

The letter « X » means that the test has not been done or the performance is not claimed.

This kind of glove does not protect against risks not written in this user instruction.

Store in a dry place, away from light. This glove is a category II PPE. It is not possible to predict their shelf life as this depends on the purpose for which they are used and the handling by the user. To put on gloves, make sure to choose the right size. The glove must be removed as soon as it is damaged or shows signs of wear. This glove must be used in a professional or industrial field only.
The CE marks means that this product is complying with the European Regulation (EU) 2016/425 concerning the Personal Protective Products.Do not use this glove if there is a risk of being caught in movable parts of device.
This glove should not be in contact with a flame.
This glove doesn't contain substances known to be carcinogenic, toxic or likely to cause allergies to sentive people.
The real use conditions may be different from the testing realized in laboratory conditions under standards requirements.
Cleaning : Excess contamination may be removed with water. Test results achieved are on new unused gloves.This glove isn't washable. When donning and doffing,gently grasp the cuff of the glove with one hand, and put the other hand into it; When take off the glove, hold the finger of the glove with one hand, the middle finger is a good choice, then gently pull it down.
Available from size 7 to size 11.

The EU declaration of conformity can be accessed through http://conformites.frsecurite.fr

Find our products range on our E-Catalogue

FR LE TRI FACILE PAPIER BAC DE TRI

Made in China

Ind 2